# Robin America, Inc.

940 Lively Boulevard, Wood Dale, IL 60191 • Phone: (630) 350-8200 • Fax: (630) 350-8212



## **SERVICE BULLETIN**

RS 344 February 2003

MODEL	SUBJECT
EH65, EH64, EH65 EH63V, EH65V, EH72	Change of Ignition Coil

#### PURPOSE:

Change in coil manufacturer (1) and start-ability improvement (2)

#### AFFECTED PRODUCTS:

All specifications (except for Onan) of EH64, EH65, EH63V, EH65V and EH72

#### • DETAIL OF CHANGE:

Refer to page 2

#### CHANGE OF PART NUMBERS and INTERCHANGEABILITY:

#### 1. Manufacturer change

No	Description	After the change		Interchan	Before the change		
INO		Part number	Qty	Individual	Set	Part number	Qty
1	Ignition Coil	263-78202-01	2	No New <del>← X →</del> Old	New ←─── Old  -	263-78201-01	2
2	Bolt & Washer AY	001-14062-50	4	No New <del>← X →</del> Old		001-14063-00	4

#### 2. Start-ability improvement

1	No	Description	After the change		Interchangeshility	Before the change	
	No Descrip	Description	Part number	Qty	Interchangeability	Part number	Qty
	1	Ignition Coil	263-78202-11	2	New Old	263-78202-01	2

#### EXECUTION:

#### Step 1

FHI production: April thru October 2002 - Serial numbers 6011938 to 6014084

RMI production: May thru October 2002

#### Step 2

FHI production: In and after October 2002 - Serial numbers 6014085 and after

RMI production: In and after October 2002

#### DETAIL OF THE CHANGE:

### **After the Change**

## **Before the Change**

#### Step 1. Manufacturer change



